

Printed : 30/01/2024

Revised : MP V1-R-2-CLP from 30/01/2024

BUTYRIC ACID

1. SECTION 1 - IDENTIFICATION OF THE SUBSTANCE/MIXTURE AND OF THE COMPANY

1.1. Product identifier

Name of the substance/mixture Item code	: BUTYRIC ACID : ACBU-1
N° CAS TSCA N° CE N° index REACH An VI N° REACH (partially)	: 107-92-6 : 203-532-3 : 607-135-00-X : Exempt <1T
IUPAC Name :	Butanoic acid
Chemical / REACH name :	Butyric acid
Molecular formula :	C4 H8 O2
Molecular weight :	88.12

1.2. Relevant identified uses of the substance or mixture and uses advised against

Use of the substance/mixture : Industrial use only

End use :

Fragrances / Cosmetic / Flavours

1.3. Details of the supplier of the safety data sheet

SAS PCW Aromagrasse - 45 bd Marcel Pagnol 06130 Grasse - FRANCE Tel : +33 (0)4 92 42 35 00 Fax : +33 (0)4 92 42 35 19 Web : www.pcwfrance.com Email : info@pcwfrance.com

Technical manager : regulatory@pcwfrance.com

1.4. Emergency telephone number

Emergency information service of the company

+33(6) 07 85 74 60 (24h/24h)

National emergency information service

INERIS : +33(8) 20 20 18 16



Printed : 30/01/2024

BUTYRIC ACID

Revised : MP V1-R-2-CLP from 30/01/2024

Anti poison Centers in France

ORFILA : +33(1) 45 42 59 59

2. SECTION 2 - HAZARDS IDENTIFICATION

2.1. Classification of the substance or mixture

GHS Classification :

(RegulationCLP)

Acute Tox. 4 (Oral)Acute toxicity oral 4Eye Dam. 1Serious eye damage / eye irritation 1Skin Corr. 1BSkin corrosion / irritation 1B

H302 - Harmful if swallowed. H314 - Causes severe skin burns and eye damage. H318 - Causes serious eye damage.

2.2. Label elements

GHS Classification :

(RegulationCLP)



Warning mention : Danger

Acute Tox. 4 (Oral)Acute toxicity oral 4Eye Dam. 1Serious eye damage / eye irritation 1Skin Corr. 1BSkin corrosion / irritation 1B

H302 - Harmful if swallowed.

H314 - Causes severe skin burns and eye damage.

H318 - Causes serious eye damage.

P260 - Do not breathe dust/fume/gas/mist/vapours/spray.

P264 - Wash hands thoroughly after handling.

P301+P312 - IF SWALLOWED: Call a POISON CENTER/doctor/... if you feel unwell.

P301+P330+P331 - IF SWALLOWED: Rinse mouth. Do NOT induce vomiting.

P301/30/31+P310 - If swallowed : Rinse mouth. Do not induce vomiting. Immediately call a poison center or doctor/physician.

P303+P361+P353 - IF ON SKIN (or hair): Take off immediately all contaminated clothing. Rinse skin with water [or shower].

P304+P340 - IF INHALED: Remove victim to fresh air and keep at rest in a position comfortable for breathing.

P305+P351+P338 - IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.



Printed : 30/01/2024

BUTYRIC ACID

Revised : MP V1-R-2-CLP from 30/01/2024

P501 - Dispose of contents/container according to the local/ regional / national / international Regulation.

2.3. Other hazards

The substance/mixture does not contain components considered to have endocrine disrupting properties according to Article 57(f) of REACH or Commission Regulation (EU) 2017/2100 or Commission Regulation (EU) 2018/605 at levels of 0,1 % or more.

Contains Butyric acid

PBT:	No Data
vPvB:	No Data
VOC Swiss - Annex 1 :	Not listed
Low VOC (CARB) :	100%
CMR (Reg. 1223/2009/EEC) :	See certificate

3. SECTION 3 - COMPOSITION INFORMATION ON INGREDIENTS

3.1. Substances

Numéro d'identification	Substance	Classes danger & Phrases H	LCS / Facteurs M / ATE	Percent %
CAS# 107-92-6 EINECS# 203-532-3 REACH# N° REACH 01-2119488986-11-xxx x / N° 1NDEX 607-135-00-X	Butyric acid	Acute Tox. 4 (Oral), Eye Dam. 1, Skin Corr. 1B H302, H318, H314	ATE (Orale) : 1630mg/kg	> 50 %

The substance/mixture does not contain components considered to have endocrine disrupting properties according to Article 57(f) of REACH or Commission Regulation (EU) 2017/2100 or Commission Regulation (EU) 2018/605 at levels of 0,1 % or more.

3.2. Mixtures

Not concerned

4. SECTION 4 - FIRST AID MEASURES

4.1. Description of first aid measures

General notes : Please refer to the risk and safety statements (section 2)

Following inhalation : If inhaled : If breathing is difficult, remove victim to fresh air and keep at rest in a position comfortable for breathing. Remove collar, belt, tie... Give artificial respiration if not breathing.

Following ingestion : If swallowed: Immediately call a POISON CENTER or doctor/physician. Rinse mouth. Do NOT induce vomiting.

Following skin contact : If on skin (or hair) or clothing rinse immediately contaminated clothing and skin with plenty of water

before removing clothes. If the symptom persists, consult a doctor.



Printed : 30/01/2024

BUTYRIC ACID

Revised : MP V1-R-2-CLP from 30/01/2024

Following eye contact : Rinse cautiously with water for several minutes (15 minutes open eyelids). Remove contact lenses, if present and easy to do. Continue rinsing. In case of disorder, consult an ophtalmologist.

Self-protection of the first aider : In lack of appropriate formation, none initiative should imply an individual risk.

4.2. Most important symptoms and effects, both acute and delayed

See section 2

4.3. Indication of any immediate medical attention and special treatment needed

See section 2

5. SECTION 5 - FIREFIGHTING MEASURES

5.1. Extinguishing media

Suitable extinguishing media : Use an extinguishing agent suitable for the surrounding fire. CO2, powder, foam, specific liquid.

Unsuitable extinguishing media : Never use a direct stream of water.

5.2. Special hazards arising from the substance or mixture

Flammability : The product is not flammable.

Prevention : Keep away from heat/sparks/open flames/hot surfaces. - No smoking.

Particular risks linked to exposure : see section 2

Hazardous combustion products :

Release of poison gases : Monoxide de carbone (CO), Dioxyde de carbon (CO2), Oxyde d'azotes (NOx), Dioxyde de soufre (SO2), Cyanures (CN)

Auto-ignition temperature (°C) :

5.3. Advice for firefighters

Fire-fighting equipment : use an appropriate personal protective equipment with an approved positive-pressure self-contained breathing apparatus.

6. SECTION 6 - ACCIDENTAL RELEASE MEASURES

6.1. Personal precautions, protective equipment and emergency procedures



Printed :

Safety Data Sheet

Revised : MP V1-R-2-CLP from 30/01/2024

30/01/2024 Call immediately the emergency personnel.

Promote adequate ventilation in the area.

For non-emergency personnel Keep them away from the area. Avoid all sources of ignition (spark of flame). Avoid skin/eye contact. Do not inhal vapours.

For emergency responders Use personal protective equipment. In case of accidental spills, wear protective gloves during the handling.

BUTYRIC ACID

6.2. Environmental precautions

Avoid the dispersion and flow of the product. Keep away from drains, surface and ground water. Inform the competent authorities if the product enters in ground or surface waters.

6.3. Methods and material for containment and cleaning up

For containment

The spillage is contained with sand or inert powder. The chemical waste is placed in sealed containers.

For cleaning up

The soiled elements (rags, absorbent papiers, filters) are immediately soaked into water. The chemical waste are rapidly treated according to the local reglementation

Other informations Only qualified personnel is allowed to clean up.

6.4. Reference to other sections

See section 8 for personal protective equipment and section 13 for waste treatment.

7. SECTION 7 - HANDLING AND STORAGE

7.1. Precautions for safe handling

Protective measures: See section 2.2



Measures to prevent fire: Do not smoke. Do not expose to excessive heat or ignition sources (spark or flame).

Measures to prevent aerosol and dust generation: Maintain adequate ventilation in the area.



Printed : 30/01/2024

BUTYRIC ACID

Revised : MP V1-R-2-CLP from 30/01/2024

Measures to protect the environment:

Avoid spreading product and keep it from spilling. Precautions or coming in contact with the ground, waterways, drains and vents.

Advice on general occupational hygiene:

Follow the general hygiene rules.

7.2. Conditions for safe storage, including any incompatibilities

Storage conditions: Store in its original packaging in a cool dry place, away from light.

<u>Technical measures:</u> Close the container after use. In case of transferring, reproduce the labelling.

Packaging materials: Preserve only in the container of origin.

Respect the general rules of incompatibility.

Storage :	Store at 25°C max. in tightly sealed original container. Avoid prolonged exposure to light, heat and air.	
Storage areas and packaging conditions :	Store in a well-ventilated area.	
Protection against the fire and the explosion :	Non-flammable	

7.3. Specific end use(s)

Wash the hands and any other zone exposed with soap and water before eating, drinking, to smoke and before leaving work.

8. SECTION 8 - EXPOSURE CONTROLS / PERSONAL PROTECTION

8.1. Control parameters

Measures of technical order : Avoid contact with eyes, skin and closes. Do not ingest. Do not inhal vapors. Use proper personal protective equipment.

Monitoring procedures : If the product contains ingredients presenting exposure limits, he can turn out necessary to make an examination followed by the persons, by the atmosphere in the workplace either bodies living to end the efficiency of the ventilation or the other control measures or estimate the need to use of the material of protection of respiratory tracts. It is important to put back you in the European standard EN 689 concerning the methods to estimate the exhibition by inhalation to the chemical agents and to the national general documents of politics relative to the methods to determine dangerous substances.

PNEC Fresh water :	No Data
PNEC Fresh water sediment :	No Data
PNEC Marine water :	No Data
PNEC Marine sediment :	No Data
PNEC Soil:	No Data



 Printed :
 30/01/2024
 BUTYRIC ACID
 Revised : MP V1-R-2-CLP from 30/01/2024

 VLEP short term mg/m3 (98/24/CE) :
 No Data
 VLEP (8h) mg/m3 (98/24/CE) :
 No Data

 DNEL - Inhalation :
 No Data
 No Data

 DNEL - Skin contact :
 No Data
 No Data

8.2. Exposure controls

Appropriate technical controls :

No special ventilation requirements. Good general ventilation should be sufficient to control worker exposure to airborne contaminants. If this product contains ingredients with exposure limits, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure.

Personal protection measures :

Personal protection :

- Hand protection: Protection not required.- Eye protection: Protection not required.- Respiratory protection: In case of insufficient ventilation, wear suitable respiratory equipment.

Respiratory protection: Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates that is necessary. Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator.

Filter apparatus (dust masks or half masks)

Type of filters

Type AX (Brown) : Organic compounds boiling point < 65°C

Type A (Brown) : Organic compounds boiling point > 65°C

Type B (Grey) : Inorganic gasses and fumes.

Type P (White) : Particles, dusts and aerosols

Hand protection : Impermeable and chemical resistant gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is necessary >8 hours before piercing : vinyle disposable.

Remark: Recommended impermeable goggles do not only depend of his matter. Other factors can have a signifiant effect on impermeability, like their thickness or specific use or temperature conditions. In all cases, matter certificates should be selected. Ask your supply if the goggles are appropriate to this use.

Eyes protection : Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists or dusts. Recommanded : Splash googles, safety glasses with side-shields.

Skin protection :Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling this product.

Body : Recommanded : lab coat (sarrau), general.

Type 3 : Liquid impermeability

Type 4 : Aerosol impermeability

Type 6 : Impermeability limited to liquid splashs

Foot : Recommanded : neoprene

Upper and sole resistant and impermeable (Hydrocarbure resistant).

9. SECTION 9 - PHYSICAL AND CHEMICAL PROPERTIES

9.1. Information on basic physical and chemical properties

Appearance : Liquid

Colour :

Liquiu

Colourless



BUTYRIC ACID	
Acrid. Unpleasant. Rancid	
[0.954 ; 0.959]	
[1.397 ; 1.399]	
-	
76	
162	
-6	
-	
-	
[99.0 ; 100.0]	
-	
1.650000 mmHg @ 25.00 °C.	
LogPow 0.790	
Yes	
Yes	
	Acrid. Unpleasant. Rancid [0.954 ; 0.959] [1.397 ; 1.399] - 76 162 -6 - [99.0 ; 100.0] - 1.650000 mmHg @ 25.00 °C. LogPow 0.790

10. SECTION 10 - STABILITY AND REACTIVITY

10.1. Reactivity

Avoid powerful oxidizing agents

10.2. Chemical stability

Stable under normal conditions.

Shelf life :

36 months, according to storage conditions

10.3. Possibility of hazardous reactions

No hazardous reactions when stored and handled according to instructions.

10.4. Conditions to avoid

Avoid any potential source of heat.

10.5. Incompatible materials

Not concerned



Printed :

Safety Data Sheet

Revised : MP V1-R-2-CLP from 30/01/2024

10.6. Hazardous decomposition products

30/01/2024

Thermal decomposition / conditions to be avoided: No decomposition if used according to specifications. **Dangerous decomposition products:** No dangerous decomposition products known.

BUTYRIC ACID

11. SECTION 11 - TOXICOLOGICAL INFORMATION

11.1. Information on toxicological

Phototoxicity :	No Data
Genotoxicity in vitro :	No Data
Genotoxicity in vivo :	No Data
LD50 Dermal (rabbit) :	No Data
LD50 oral (rat) :	No Data
Skin irritation :	Causes Burns
Respiratory or Skin sensitization :	Gases and vapours in high concentrations can irritate the respiratory system.
Serious eye damage/irritation :	Causes Burns
Eyes irritation :	Irritant
12 SECTION 12 - ECOLOGI	

12.1. Toxicity

Do not leave the product, even diluted or in great quantity, penetrate the ground water, water or the drains.

LC50 Ecotoxicity :	No Data
CE50 (Aquatic fauna) :	No Data
EC50 Ecology :	No Data
CE50 (Aquatic flora) :	No Data
No observable adverse effect level (NOAEL) :	No Data
No observed effect level (NOEL) :	No Data
12.2. Persistence and dec	gradability
Biodegradability :	No Data
12.3. Bioaccumulative po	tential
Bioaccumulation (LogPow) :	0.790
12.4. Mobility in soil	

PNEC sol : No Data



Printed : 30/01/2024

BUTYRIC ACID

Revised : MP V1-R-2-CLP from 30/01/2024

12.5. Results of PBT and vPvB assessment

vPvB : No Data

PBT : No Data

12.6. Other adverse effects

The product does not contain substances identified as having endocrine disrupting properties (environment) in concentrations equal to or greater than 0.1% (m/m).

No data

13. SECTION 13 - DISPOSAL CONSIDERATIONS

13.1. Waste treatment methods

Product : Does not have to be evacuated with the refuse. Not let it penetrate in the sewers. **Not cleaned packing :** Evacuation according to local reglementation.

14. SECTION 14 - TRANSPORT INFORMATION

ADR/ADN/RID:



IMDG:



IATA:



14.1. UN number

ADR/ADN/RID : 2820 (Tunnel code (E)) IMDG:2820 IATA :2820

14.2. UN proper shipping name



Printed : 30/01/2024

BUTYRIC ACID

Revised : MP V1-R-2-CLP from 30/01/2024

ADR/ADN/RID : BUTYRIC ACID IMDG:BUTYRIC ACID IATA :BUTYRIC ACID

14.3. Transport hazard class(es)

ADR/ADN/RID : 8 IMDG:8 IATA :8

14.4. Packing group

ADR/ADN/RID : III IMDG:III IATA :III

14.5. Environmental hazards

IMDG : Not concerned

14.6. Special precautions for user

Avoid any direct contact with the product.

Precautions of use :

Avoid any direct contact with the product.

14.7. Transport in bulk according to Annex II of MARPOL73/78 and the IBC Code

(Except particular case)

IBC Liquid substances Metal (31A, 31B, 31N) Plastic (31H1, 31H2)

<u>GRV Solid substances</u> Metal (11A, 11B, 21A, 21N) Plastic (11H1, 11H2, 21H1, 21H2)

15. SECTION 15 - REGULATORY INFORMATION

15.1. Safety, health and environmental regulations/legislation specific for the substance or mixture

WGK :

1-ID41

15.2. Chemical safety assessment

Exposure assessment :

16. SECTION 16 - OTHER INFORMATIONS

Full H sentenses text in point 3 :

- H302 Harmful if swallowed.
- H314 Causes severe skin burns and eye damage.



30/01/2024 Revised : MP V1-R-2-CLP from 30/01/2024 Printed : **BUTYRIC ACID**

H318 Causes serious eye damage.

_____ _____ Key literature references and sources for data Sources for data : Information from supplier Literature references : ECHA

Literature references EU : Reg. 1272/2008 ----------

Safety data sheet according to REG. 1272/2008/CE and its amendings These indications are founded on the current state of our knowledge, but do not constitute a guarantee as for the properties of the product and do not give place to a contractual legal report. _____ -----

Modified points : 1.2 2.1 2.2 2.3 3.1 7.1 8.2 9.1 11.1 12.6 14 14.1 14.2 14.3 14.4 14.5 14.6 16